

### DEPARTMENT OF THE ARMY

CORPS OF ENGINEERS, NEW ORLEANS DISTRICT P.O. BOX 60267 NEW ORLEANS, LOUISIANA 70160-0267

FEB 2 4 2016

EXHIBIT 11 WETLANDS DELINEATION

ATTENTION OF
Operations Division
Surveillance and Enforcement Section

Mr. Bart Pittman
Pittman Environmental Services
PO Box 1926
Purvis, Mississippi 39475

REPLY TO

Dear Mr. Pittman:

Reference is made to your request, on behalf of Pan American Engineers, for a U.S. Army Corps of Engineers' jurisdictional determination on property located in Sections 34 and 35, Township 4 North, Range 2 West, Rapides Parish, Louisiana (enclosed map). Specifically, this property is identified as a 45 acre tract on and north of the intersection of Frank Andrews Blvd and Vandenburg Drive in England Airpark.

Based on review of recent maps, aerial photography, and soils data, we have determined that part of the property is wetland and may be subject to Corps' jurisdiction. The approximate limits of the wetland are designated in red on the map. A Department of the Army (DA) permit under Section 404 of the Clean Water Act will be required prior to the deposition or redistribution of dredged or fill material into wetlands that are waters of the United States. Additionally, a DA permit will be required if you propose to deposit dredged or fill material into other waters subject to Corps' jurisdiction. Other waters that may be subject to Corps' jurisdiction are indicated in blue on the map.

Additionally, federal projects are known to exist in this area that may require further engineering review prior to the initiation of any activities on this site. For more information, please contact Russel Beauvais of our Operations Division at (225) 492-2169.

You and your client are advised that this preliminary jurisdictional determination is valid for a period of 5 years from the date of this letter unless new information warrants revision prior to the expiration date or the District Commander has identified, after public notice and comment, that specific geographic areas with rapidly changing environmental conditions merit re-verification on a more frequent basis.

Should there be any questions concerning these matters, please contact Dr. Rosie Schwamenfeld at (337) 291-3045 and reference our Account No. MVN-2015-01676-SR. If you have specific questions regarding the permit process or permit applications, please contact our Western Evaluation Section at (504) 862-2261.

Sincerely,

Martin S. Mayer

Chief, Regulatory Branch

Blut a Hoffmer

Enclosures

FIGURE 1 ary Wetland Delineation Sections 34 & 35, T-4N, R-2W ximately 45 Acres USACE Rapides Parish, LA and Airpark, Site E2 Account # MVN-2015-01676-5R For Bart Pillman 31.33408 -92.53044 **AEX** MVN-2014-00087-5 U.S. ARMY CORPS OF ENGINEERS PRELIMINARY JURISDICTIONAL DETERMINATION WANK ANDREWS B Legend . Non wetland E2 Site Limits +/-45.0 Acres **Sec 404**Wetland Drain +/-0.79 Acres Sec 404 Water Data Points

Old Railroad

#### PRELIMINARY JURISDICTIONAL DETERMINATION FORM

This preliminary JD finds that there "may be" waters of the United States on the subject project site, and identifies all aquatic features on the site that could be affected by the proposed activity, based on the following information:

District Office New Orleans District File/ORM #	2015-01676-SR	PJD Date: Feb 18, 2016		
State LA City/County Rapides	Nemal			
Nearest Waterbody: unnamed tributary	Address of Person	Bart Pittman Pittman Environmental Services		
Location: TRS, LatLong or UTM: T4N, R2W, Section 34 and 35 Lat: 31.33408, Long: -92.53044	Requesting PJD	PO Box 1926 Purvis, MS 39475		
Identify (Estimate) Amount of Waters in the Review Area:  Non-Wetland Waters:  Stream Flow:  1350 linear ft width acres  Per. (seasonal)	Gotton to Waters.	Tidal: n-Tidal:		
Wetlands: 0.70 acre(s) Cowardin Class: Palustrine, emergent	☐ Office (Desk) Determina ☐ Field Determination:	Date of Field Trip:		
Maps, plans, plots or plat submitted by or on behalf of Data sheets prepared/submitted by or on behalf of the Office concurs with data sheets/delineation Office does not concur with data sheets/delineation Data sheets prepared by the Corps Corps navigable waters' study:  U.S. Geological Survey Hydrologic Atlas:  USGS NHD data.  7 USGS 8 and 12 digit HUC maps.  U.S. Geological Survey map(s). Cite quad name:  National wetlands inventory map(s). Cite name:  State/Local wetland inventory map(s):  FEMA/FIRM maps:  100-year Floodplain Elevation is:	e applicant/consultant. report. ineation report.  pides			
Photographs: Aerial (Name & Date): CIR: 98, 0-1 F  Other (Name & Date): Google Earth	0, 13			
Previous determination(s). File no. and date of responsible To Other information (please specify):	nse letter:	·		
MPORTANT NOTE: The information recorded on this form has not necessarily SCHWAMENFELD.ROSE.EL Digitally signed by SCHWAMENFELD ROSE ELLEN PALLUMBO 1388591702 ON: CHUS, GOUL S Government, our DOO, our PKI, our Lose SCHWAMENFELD ROSE ELLEN PALLUMBO 13885 Date: 2016 02 18 17:22:29 -05:00	usa. seiroz <u>Bart Pittman by</u> l	mail dated 8-4-15		
Signature and Date of Regulatory Project Manager (REQUIRED)		erson Requesting Preliminary JD taining the signature is impracticable)		

EXPLANATION OF PRELIMINARY AND APPROVED JURISDICTIONAL DETERMINATIONS:

1 The Corps of Engineers believes that there may be jurisdictional waters of the United States on the subject site, and the permit applicant or other affected party who requested this preliminary JD is hereby advised of his or her option to request and obtain an approved jurisdictional determination (JD) for that site. Nevertheless, the permit applicant or other person who requested this preliminary JD has declined to exercise the option to obtain an approved JD in this instance and at this time.

2 In any circumstance where a permit applicant obtains an individual permit, or a Nationwide General Permit (NWP) or other general permit verification requiring "preconstruction notification" (PCN), or requests verification for a non-reporting NWP or other general permit, and the permit applicant has not requested an approved JD for the activity, the permit applicant is hereby made aware of the following: (1) the permit applicant has elected to seek a permit authorization based on a preliminary JD, which does not make an official determination of jurisdictional waters; (2) that the applicant has the option to request an approved JD before accepting the terms and conditions of the permit authorization, and that basing a permit authorization on an approved JD could possibly result in less compensatory mitigation being required or different special conditions; (3) that the applicant has the right to request an individual permit rather than accepting the terms and conditions of the NWP or other general permit authorization; (4) that the applicant can accept a permit authorization and thereby agree to comply with all the terms and conditions of that permit, including whatever mitigation requirements the Corps has determined to be necessary, (5) that undertaking any activity in reliance upon the subject pennit authorization without requesting an approved JD constitutes the applicant's acceptance of the use of the preliminary JD, but that either form of JD will be processed as soon as is practicable; (6) accepting a permit authorization (e.g., signing a proffered individual permit) or undertaking any activity in reliance on any form of Corps permit authorization based on a preliminary JD constitutes agreement that all wellands and other water bodies on the site affected in any way by that activity are jurisdictional waters of the United States, and precludes any challenge to such jurisdiction in any administrative or judicial compliance or enforcement action, or in any administrative appeal or in any Federal court; an

* 1. TH	NOTIFICATION OF ADM	INISTRATIVE APPEAL OPTIONS AN REQUEST FOR APPEAL	D PROCESS	AND
Applicant	: Pan American Engineers	File No.: MVN-2015-01676-SR	Date:	FFR 2 4 2016
Attached is	S:			See Section below
INITIAL PROFFERED PERMIT (Standard Permit or Letter of permission)				A
PROFFERED PERMIT (Standard Permit or Letter of permission)				В
P	C			
A	PPROVED JURISDICTIONAL DETE	RMINATION		D
✓ PI	RELIMINARY JURISDICTIONAL DE	ETERMINATION		E

SECTION I - The following identifies your rights and options regarding an administrative appeal of the above decision. Additional information may be found at http://usace.army.mil/inet/functions/cw/cecwo/reg or Corps regulations at 33 CFR Part 331.

- A: INITIAL PROFFERED PERMIT: You may accept or object to the permit.
- ACCEPT: If you received a Standard Permit, you may sign the permit document and return it to the district engineer for final authorization. If you received a Letter of Permission (LOP), you may accept the LOP and your work is authorized. Your signature on the Standard Permit or acceptance of the LOP means that you accept the permit in its entirety, and waive all rights to appeal the permit, including its terms and conditions, and approved jurisdictional determinations associated with the permit.
- OBJECT: If you object to the permit (Standard or LOP) because of certain terms and conditions therein, you may request that the permit be modified accordingly. You must complete Section II of this form and return the form to the district engineer. Your objections must be received by the district engineer within 60 days of the date of this notice, or you will forfeit your right to appeal the permit in the future. Upon receipt of your letter, the district engineer will evaluate your objections and may: (a) modify the permit to address all of your concerns, (b) modify the permit to address some of your objections, or (c) not modify the permit having determined that the permit should be issued as previously written. After evaluating your objections, the district engineer will send you a proffered permit for your reconsideration, as indicated in Section B below.
- B: PROFFERED PERMIT: You may accept or appeal the permit
- ACCEPT: If you received a Standard Permit, you may sign the permit document and return it to the district engineer for final
  authorization. If you received a Letter of Permission (LOP), you may accept the LOP and your work is authorized. Your
  signature on the Standard Permit or acceptance of the LOP means that you accept the permit in its entirety, and waive all rights
  to appeal the permit, including its terms and conditions, and approved jurisdictional determinations associated with the permit.
- APPEAL: If you choose to decline the proffered permit (Standard or LOP) because of certain terms and conditions therein, you may appeal the declined permit under the Corps of Engineers Administrative Appeal Process by completing Section II of this form and sending the form to the division engineer. This form must be received by the division engineer within 60 days of the date of this notice.
- C: PERMIT DENIAL: You may appeal the denial of a permit under the Corps of Engineers Administrative Appeal Process by completing Section II of this form and sending the form to the division engineer. This form must be received by the division engineer within 60 days of the date of this notice.
- D: APPROVED JURISDICTIONAL DETERMINATION: You may accept or appeal the approved JD or provide new information.
- ACCEPT: You do not need to notify the Corps to accept an approved JD. Failure to notify the Corps within 60 days of the date of this notice, means that you accept the approved JD in its entirety, and waive all rights to appeal the approved JD.
- APPEAL: If you disagree with the approved JD, you may appeal the approved JD under the Corps of Engineers Administrative Appeal Process by completing Section II of this form and sending the form to the division engineer. This form must be received by the division engineer within 60 days of the date of this notice.
- E: PRELIMINARY JURISDICTIONAL DETERMINATION: You do not need to respond to the Corps regarding the preliminary JD. The Preliminary JD is not appealable. If you wish, you may request an approved JD (which may be appealed), by contacting the Corps district for further instruction. Also you may provide new information for further consideration by the Corps to reevaluate the JD.

		· v.
SECTION II - REQUEST FOR APPEAL or OBJECTIONS TO A	The state of the s	and the second s
REASONS FOR APPEAL OR OBJECTIONS: (Describe your reproffered permit in clear concise statements. You may attach add objections are addressed in the administrative record.)		
•		
ADDITIONAL INFORMATION: The appeal is limited to a revie	w of the administrative record, the	Corps memorandum for the
record of the appeal conference or meeting, and any supplemental	information that the review office	r has determined is needed to
clarify the administrative record. Neither the appellant nor the Co		
you may provide additional information to clarify the location of i POINT OF CONTACT FOR QUESTIONS OR INFORMATION:		ininistrative record.
	If you only have questions regar	ding the appeal process you may
process you may contact:	also contact the Division Engine	er through:
Mr. Rob Heffner	Mr. Thomas McCabe	
Chief, Surveillance and Enforcement Section	Administrative Appeals Revi	ew Officer
U.S. Army Corps of Engineers, New Orleans District	Mississippi Valley Division	
P.O. Box 60267	P.O. Box 80 (1400 Walnut St	reet)
New Orleans, LA 70160-0267	Vicksburg, MS 39181-0080 601-634-5820 FAX: 601-6	624 5916
504-862-1288	001-034-3820 FAX. 001-0	334-3810
RIGHT OF ENTRY: Your signature below grants the right of ent		
consultants, to conduct investigations of the project site during the notice of any site investigation, and will have the opportunity to page 1.		
notice of any site investigation, and will have the opportunity to pa	Date:	Telephone number:
No. of the contract of the con		
Signature of appellant or agent.		

P.O. Box 1926 Purvis. MS 39475 Phone: 601-297-2487

August 3, 2015

Mr. Kyle Randall, PE Pan American Engineers, LLC 1717 Jackson Street Alexandria, LA 71301

RE: England Airpark, Site E2 Approximately 45 Acres Rapides Parish, Louisiana

Dear Mr. Randall:

Pursuant to your request, a preliminary wetland delineation has been conducted for the above referenced site. Approximately 0.79 acres of the site was delineated as jurisdictional wetland (wetland drain). An additional 0.39 acres of vegetated ditch was delineated as potentially jurisdictional. The 0.39 acres of vegetated ditch has sufficient wetland indicators and similar features that I have delineated within other sites have been determined jurisdictional, the fact that these are man-made storm water conveyance features within non-wetlands offer a possibility that the COE might not consider them as jurisdictional. I did notice some small "borderline" areas with sedge species. These small pockets did not exhibit sufficient hydrology indicators at time of visit and were likely created by past disturbance. Although not likely, it is possible that the COE could visit the site to review my delineation and consider some of these "borderline" areas to be jurisdictional wetland.

This delineation is preliminary; it is the responsibility of the U.S. Army Corps of Engineers to issue a jurisdictional determination. I will await your notice to proceed in sending a copy of this report to the COE for jurisdictional determination.

If you have any questions, or need additional information please contact me at (601) 297-2487.

Sincerely,

Bart A. Pittman

**Environmental Specialist** 

Pittman Environmental Services, LLC

But a. Pittim

P.O. Box 1926 Purvis. MS 39475 Phone: 601-297-2487

Preliminary Wetland Delineation England Site E2 Approximately 45 Acres Rapides Parish, Louisiana **August 3, 2015** 

#### INTRODUCTION

At the request of the Pan American Engineers, a preliminary wetland delineation has been conducted for approximately 45 acres located in Sections 34 & 35, Township 4 North, Range 2 West, Rapides Parish Louisiana. The site is located within the England Airpark and was historically utilized for tank farm and rail spur. A recent Jurisdictional Determination (MVK-2014-00087-SC) was issued for property adjacent to the east. The approximate center coordinates of the site are 31.334082, -92.530449. The attached maps depict the exact location and extent of the approximately 45 acre site. This report will describe the results of a preliminary wetland delineation conducted for the said property to determine the presence and approximate extent of jurisdictional wetlands and "waters of the U.S." as defined in Section 404 of the Clean Water Act. The onsite wetland delineation was conducted by Mr. Bart Pittman on July 29<sup>th</sup> and 30<sup>th</sup>, 2015.

#### SITE DESCRIPTION

The ±45 acre site is located within the England Airpark and was until recently utilized for a tank farm with transecting rail spur. The tank farm and a portion of the rail spur have been removed. Industrial development surrounds the site with railroad along the western limits. With exception of tree line along the eastern and northern property limits, the entire site is comprised of herbaceous species. The site is nearly level to slightly sloping. The NRCS Web Soil Survey indicates the primary soil units within the site as Coushatta silt loam (Nd) and Coushatta silty clay loam (Nw). Pictures (Attachment 2) depict the current site conditions.

#### METHODOLOGY

Methods utilized for identifying and delineating wetlands follow procedures outlined in Part IV of the "Corps of Engineers Wetlands Delineation Manual" dated January 1987 and the Atlantic/Gulf Cost Plain Regional Supplement. Wetland Delineation Data Forms (Atlantic and Gulf Cost Plain Region) were completed for each vegetative community represented within the property. These attached data forms (**Attachment 3**) provide a listing of parameters/indicators to

P.O. Box 1926 Purvis, MS 39475 Phone: 601-297-2487

differentiate jurisdictional wetlands from non-wetlands. The completed forms confirm the presence or absence of the three required wetland criteria; hydrophytic vegetation, wetland hydrology, and hydric soils. The approximate location of each data point is shown on the attached preliminary wetland delineation map, (**Attachment 1**). The site was pedestrian surveyed for visual indicators of potential wetlands; soil profiles were examined in suspect areas to determine if any hydrology/hydric soil indicators were present.

#### **RESULTS**

Once the presence and location of wetland was established, the boundaries were flagged. After flagging of boundaries was completed, mapping of the wetland areas was preformed by use of a sub-meter GPS, (Ashtech Mobile Mapper). GPS data was overlaid with aerial imagery and the site limits in ArcMap 10.1 to provide the approximate location and extent of delineated features as depicted on the attached preliminary wetland delineation map, (**Attachment 1**).

After careful field review of the subject property and all available sources of information, approximately 0.79 acres of the site was delineated as jurisdictional wetland. An additional 0.39 acres of vegetated ditch was delineated as potentially jurisdictional. The location of delineated features and data points are shown in **Attachment 1**.

#### Jurisdictional Wetland/Drain

One wetland drain (approximately 0.79 acres) transects the site flowing northwest to Big Bayou. This drain is comprised of herbaceous vegetation with some pools of shallow inundation. FACW and OBL species is dominant within this drain. This drain collects storm water from smaller ditches that drain developed areas south of the site. Data point #4 was recorded within this wetland area.

#### **Potentially Jurisdictional Ditch**

Two vegetated ditches (approximately 0.39 acres combined) were delineated within the site. The two ditches drain storm water from the developed areas south of the site to the larger wetland drain. These ditches were created for storm water conveyance and are potentially jurisdictional.

P.O. Box 1926 • Purvis, MS 39475 • Phone: 601-297-2487

#### **Herbaceous Non-Wetland**

The majority of the site is comprised of well drained, herbaceous non-wetland. Four non-wetland Data Points were recorded within the site. Dominant species include *Sorghum halepense*, *Ambrosia spp.*, *Setaria spp.*, *Campsis radicans*, and *Vernonia spp.* Hydrology and hydric soil indicators were absent within the delineated non-wetlands.

#### **SUMMARY**

Based upon careful review of all available data and an onsite inspection, approximately 0.79 acres of the site was delineated as jurisdictional wetland. An additional 0.39 acres of vegetated ditch was delineated as potentially jurisdictional. The attached wetland delineation data forms (**Attachment 3**) confirm the conclusion of the preliminary study, indicating the presence or absence of sufficient wetland criteria at each data point. The location of delineated areas and of the data points are shown on the preliminary wetland delineation maps, **Attachment 1**.

This wetland delineation is preliminary and should not be interpreted as a final determination. The responsibility of a final wetland determination is that of the U.S. Army Corps of Engineers, New Orleans District.

Please call (601)-297-2487 if you have any questions or need additional information regarding this study.

Sincerely,

Bart A. Pittman


**Environmental Specialist** 


Pittman Environmental Services, LLC

But a. Pittim

# Pittman Environmental Services, LLC P.O. Box 1926 • Purvis, MS 39475 • Phone: 601-297-2487

## **ATTACHMENT 1 MAPS**







#### MAP LEGEND

#### Area of Interest (AOI) Transportation Area of Interest (AOI) Rails Soils Interstate Highways Soil Rating Polygons **US Routes** Hydric (100%) Major Roads Hydric (66 to 99%) Local Roads Hydric (33 to 65%) Background Hydric (1 to 32%) Aerial Photography Not Hydric (0%) Not rated or not available Soil Rating Lines Hydric (100%) Hydric (66 to 99%) Hydric (33 to 65%) Hydric (1 to 32%) Not Hydric (0%) Not rated or not available Soil Rating Points Hydric (100%) Hydric (66 to 99%) Hydric (33 to 65%) Hydric (1 to 32%) Not Hydric (0%) Not rated or not available **Water Features** Streams and Canals

#### MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:24,000.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service Web Soil Survey URL: http://websoilsurvey.nrcs.usda.gov Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Rapides Parish, Louisiana Survey Area Data: Version 10, Sep 26, 2014

Soil map units are labeled (as space allows) for map scales 1:50,000 or larger.

Date(s) aerial images were photographed: Feb 12, 2011—Mar 15, 2011

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

## **Hydric Rating by Map Unit**

Hydric Rating by Map Unit— Summary by Map Unit — Rapides Parish, Louisiana (LA079)							
Map unit symbol	Map unit name	Rating	Acres in AOI	Percent of AOI			
MnA	Moreland clay, 0 to 1 percent slopes, rarely flooded	1	0.0	0.0%			
Nd	Coushatta silt loam, 0 to 1 percent slopes	1	37.5	78.9%			
Nw	Coushatta silty clay loam, 0 to 1 percent slopes	1	10.0	21.1%			
Totals for Area of Inter	rest	47.5	100.0%				

# Pittman Environmental Services, LLC P.O. Box 1926 • Purvis, MS 39475 • Phone: 601-297-2487

## **ATTACHMENT 2 SITE PHOTOGRAPHS**



Southern portion of site, facing east



Facing south from northern limits, railroad to right

Pittman Environmental	PROJECT:	
Services, LLC	E2 Site-England Airpark, Rapides Parish Louisiana	
Bervices, LLC	TITLE:	PHOTOS
	SITE PHOTOGRAPHS	1-2



Wooded area of DP-1, northern property line



Soil matrix at DP-1

Pittman Environmental	PROJECT:	
Services, LLC	E2 Site-England Airpark, Rapides Parish Louisiana	
Scivices, LLC	TITLE:	PHOTOS
	SITE PHOTOGRAPHS	3-4



DP-2 facing south



Soil matrix at DP-2

Pittman Environmental	PROJECT:  E2 Site-England Airpark, Rapides Parish Louisiana				
Services, LLC	SITE PHOTOGRAPHS	PHOTOS 5 6			
	SITE PHOTOGRAPHS	5-6			



DP-4, Wetland Drain facing NW



Soil matrix at DP-4

Pittman Environmental	PROJECT:	
Services, LLC	E2 Site-England Airpark, Rapides Parish Louisiana	
Bei vices, LLC	TITLE:	PHOTOS
	SITE PHOTOGRAPHS	7-8



Wet Ditch facing North



Facing north from DP-5

Pittman Environmental	PROJECT:	
Services, LLC	E2 Site-England Airpark, Rapides Parish Louisiana	
Scivices, LLC	TITLE:	PHOTOS
	SITE PHOTOGRAPHS	9-10

# Pittman Environmental Services, LLC P.O. Box 1926 • Purvis, MS 39475 • Phone: 601-297-2487

## **ATTACHMENT 3 DATA FORMS**

## WETLAND DETERMINATION DATA FORM – Atlantic and Gulf Coastal Plain Region

Project/Site: Site E2, +/-45 Acres City/	/County: Alexandria/Rapides	Sampling Date: 07/30/2015
Applicant/Owner: England Authority		Sampling Point: Data Point 1
• •	tion, Township, Range: Section 34 T-4N	•
	al relief (concave, convex, none): nearly lo	
Subregion (LRR or MLRA): Lat:		
Soil Map Unit Name: Coushatla silty clay loam (Nw)		
	NWI classit	
Are climatic / hydrologic conditions on the site typical for this time of year?		
Are Vegetation, Soil, or Hydrology significantly distu		" present? Yes No
Are Vegetation, Soil, or Hydrology naturally problem	natic? (If needed, explain any answ	<i>e</i> rs in Remarks.)
SUMMARY OF FINDINGS - Attach site map showing sa	mpling point locations, transect	s, important features, etc.
Literature Processor Vice A		
Hydrophytic Vegetation Present? Yes ✓ No Hydric Soil Present? Yes No	Is the Sampled Area	
Wetland Hydrology Present? Yes No _✓	within a Wetland? Yes	No
Remarks:		
Wooded strip along northern boundary		
Wooded Strip along northern boundary		
HYDROLOGY		
Wetland Hydrology Indicators:	Secondary Indi	cators (minimum of two required)
Primary Indicators (minimum of one is required; check all that apply)	Surface Sc	oil Cracks (B6)
Surface Water (A1) Aquatic Fauna (B13)	Sparsely V	egetated Concave Surface (B8)
High Water Table (A2) Marl Deposits (B15) (LF	RR U) Drainage P	Patterns (B10)
Saturation (A3) Hydrogen Sulfide Odor		Lines (B16)
	along Living Roots (C3) Dry-Season	n Water Table (C2)
Sediment Deposits (B2) Presence of Reduced Ir		urrows (C8)
Drift Deposits (B3) Recent Iron Reduction i	• • •	Visible on Aerial Imagery (C9)
Algal Mat or Crust (B4) Thin Muck Surface (C7)		ic Position (D2)
Iron Deposits (B5) Other (Explain in Rema		guitard (D3)
Inundation Visible on Aerial Imagery (B7)		al Test (D5)
Water-Stained Leaves (B9) Field Observations:	Spriagrium	moss (D8) (LRR T, U)
Surface Water Present? Yes No _ ✓ Depth (inches):		
Water Table Present? Yes No Depth (inches):		
Saturation Present? Yes No Depth (inches):		ent? Yes No_✓_
(includes capillary fringe)	Wettand Trydrology Fresc	,
Describe Recorded Data (stream gauge, monitoring well, aerial photos, pr	revious inspections), if available:	
Remarks:		
No saturation, well drained.		

Sampling Point: \_\_

	Absolute	Dominant	Indicator	Dominance Test worksheet:
Tree Stratum (Plot size:)		Species?		Number of Dominant Species
1. Liquidambar styraciflua	30	yes	<u>FAC</u>	That Are OBL, FACW, or FAC: 8 (A)
2. Celtis laevigata	<u> 25 </u>	yes	FACW	Total Number of Dominant
3				Species Across All Strata: 8 (B)
4				
5.				Percent of Dominant Species That Are OBL, FACW, or FAC: 100 (A/B)
6.				That He OBE, I ACW, OF IAC (AB)
7.				Prevalence Index worksheet:
				Total % Cover of: Multiply by:
8				OBL species x 1 =
5004 54 4 4		= Total Cov		FACW species x 2 =
50% of total cover:	20% of	total cover	:	FAC species x 3 =
Sapling/Shrub Stratum (Plot size:)	40		EAC	FACU species x 4 =
1. Diospyros virginiana	_ 10	yes	FAC	UPL species x 5 =
2. Celtis laevigata	5	<u>ves</u>	FACW	Column Totals: 0 (A) 0 (B)
3. Cornus drummondii	_ <u>10</u>	yes	FAC	Column Totals. (A)
4				Prevalence Index = B/A =
5				Hydrophytic Vegetation Indicators:
6				1 - Rapid Test for Hydrophytic Vegetation
7.				2 - Dominance Test is >50%
8				3 - Prevalence Index is ≤3.0¹
	~=	= Total Cov		
50% of total cover:				Problematic Hydrophytic Vegetation¹ (Explain)
Herb Stratum (Plot size:)				1
1 Toxicodendron radicans	4	yes	FAC	Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.
''	4	ves	FAC	
	$-\frac{7}{3}$	yes	FAC	Definitions of Four Vegetation Strata:
·	- 8		FAC	Tree – Woody plants, excluding vines, 3 in. (7.6 cm) or
4. Ambrosia trifida		yes	<u>FAC</u>	more in diameter at breast height (DBH), regardless of
5				height.
6				Sapling/Shrub – Woody plants, excluding vines, less
7				than 3 in. DBH and greater than 3.28 ft (1 m) tall.
8				Herb – All herbaceous (non-woody) plants, regardless
9				of size, and woody plants less than 3.28 ft tall.
10				Manda da Allacada
11.				Woody vine – All woody vines greater than 3.28 ft in height.
12.				g.n.
12.	19	= Total Cov	/er	
50% of total cover:				
	20% 0	total cover		
Woody Vine Stratum (Plot size:)				
1				
2				
3				
4				
5				Hydrophytic
	0	= Total Cov	/er	Vegetation
50% of total cover:	20% of	f total cover	:	Present? Yes Vo No No
Remarks: (If observed, list morphological adaptations bel	ow).			
, , , , ,	,			

DP-1

Sampling Point: \_

SOIL

Profile Desc	ription: (Describe	to the depth	needed to docun	nent the ir	ndicator	or confirn	n the absence of inc	dicators.)
Depth	Matrix		Redo	x Features	<b>;</b>			
(inches)	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>	Texture	Remarks
0-5	5 YR 4/3	97%				IVI	clay loam	
5-19	5YR 4/4	97%					clay loam	
<del></del>	3117 4/4						——————————————————————————————————————	
								-
1= 0 0			- d d NA - 4-2 NAC		010-		21	Name Limin v. M. Madrica
	oncentration, D=De					ains.		Pore Lining, M=Matrix.
	ndicators: (Appli	cable to all Lr						roblematic Hydric Soils <sup>3</sup> :
Histosol			Polyvalue Be				· —	
	ipedon (A2)		Thin Dark Su	, ,				A10) (LRR S)
Black His	, ,		Loamy Mucky			(O)		rtic (F18) (outside MLRA 150A,B)
	n Sulfide (A4)		Loamy Gleye	d Matrix (I	F2)			oodplain Soils (F19) (LRR P, S, T)
	l Layers (A5)		Depleted Mat	rix (F3)			<del></del>	Bright Loamy Soils (F20)
	Bodies (A6) (LRR F		Redox Dark S	•	*		(MLRA 15	•
5 cm Mu	cky Mineral (A7) <b>(L</b>	RR P, T, U)	Depleted Dar	k Surface	(F7)		Red Parent	Material (TF2)
Muck Pre	esence (A8) (LRR I	J)	Redox Depre	ssions (F8	3)		Very Shallov	v Dark Surface (TF12)
1 cm Mu	ck (A9) (LRR P, T)		Marl (F10) (L	RR U)			Other (Expla	in in Remarks)
Depleted	l Below Dark Surfac	ce (A11)	Depleted Och	nric (F11) (	(MLRA 1:	51)		
Thick Da	rk Surface (A12)		Iron-Mangan	ese Masse	s (F12) (	LRR O, P,	, <b>T)</b> <sup>3</sup> Indicators	of hydrophytic vegetation and
Coast Pr	airie Redox (A16) (	MLRA 150A)	Umbric Surfa	ce (F13) (I	LRR P, T	, U)	wetland h	nydrology must be present,
Sandy M	lucky Mineral (S1) (	LRR O, S)	Delta Ochric	(F17) <b>(ML</b>	RA 151)		unless di	sturbed or problematic.
Sandy G	leyed Matrix (S4)		Reduced Ver	tic (F18) <b>(I</b>	MLRA 15	0A, 150B)	)	
Sandy R	edox (S5)		Piedmont Flo	odplain So	oils (F19)	(MLRA 14	49A)	
Stripped	Matrix (S6)		Anomalous B	right Loan	ny Soils (	F20) <b>(MLF</b>	RA 149A, 153C, 153I	D)
Dark Sur	face (S7) (LRR P,	S, T, U)						
Restrictive L	ayer (if observed)	:						
Type:								
	ches):		_				Hydric Soil Pres	ent? Yes ∐ No 【✔】 │
			_				Tiyano Con Troo	
Remarks:								

## WETLAND DETERMINATION DATA FORM – Atlantic and Gulf Coastal Plain Region

Project/Site: Site E2, +/-45 Acres	City/Count	ty: Alexandria/Rap	oides	Sampling Date: 07/30/2015		
Applicant/Owner: England Authority				Sampling Point: Data Point 2		
	Section, T					
				vel Slope (%): 1-2		
Subregion (LRR or MLRA):				Datum: NAD 83		
Soil Map Unit Name: Coushatta silt loam (Nd)	Lat.		NWI classific			
Are climatic / hydrologic conditions on the site typical for t	his time of year? Ves					
				oresent? Yes <u>√</u> No		
Are Vegetation, Soil, or Hydrology						
Are Vegetation, Soil, or Hydrology	_ naturally problematic?	(If needed, e	explain any answe	rs in Remarks.)		
SUMMARY OF FINDINGS - Attach site ma	p showing sampli	ng point location	ns, transects	, important features, etc.		
Hydrophytic Vegetation Present?  Hydric Soil Present?  Wetland Hydrology Present?  Yes  Yes	No	the Sampled Area	Yes	No		
Remarks:						
HYDROLOGY						
Wetland Hydrology Indicators:			Secondary Indica	ators (minimum of two required)		
Primary Indicators (minimum of one is required; check a	ll that apply)		Surface Soil	Cracks (B6)		
Surface Water (A1) Aquat	ic Fauna (B13)		Sparsely Vegetated Concave Surface (B8)			
	Deposits (B15) (LRR U)		Drainage Patterns (B10)			
	gen Sulfide Odor (C1)		Moss Trim Lines (B16)			
	zed Rhizospheres along					
	nce of Reduced Iron (C	*	Crayfish Burrows (C8)			
	nt Iron Reduction in Tille	ed Soils (C6)				
	Muck Surface (C7)			Position (D2)		
Iron Deposits (B5) Other Inundation Visible on Aerial Imagery (B7)	(Explain in Remarks)		Shallow Aqu FAC-Neutral	` '		
Water-Stained Leaves (B9)				noss (D8) (LRR T, U)		
Field Observations:			Opinagrium in	loss (Do) (Errit 1, O)		
	Pepth (inches):					
Water Table Present? Yes No V						
Saturation Present? Yes No			lydrology Preser	nt? Yes No_✓		
(includes capillary fringe)	· ` `			100		
Describe Recorded Data (stream gauge, monitoring wel	l, aerial photos, previou	s inspections), if ava	ilable:			
Remarks:						
No saturation, well drained.						

$\Box$	Р	-2
U	Г	-2

<b>VEGETATION (Four Strata)</b> – Use scientific na	ames of pl	lants.		Sampling Point:	
		Dominant		Dominance Test worksheet:	
Tree Stratum (Plot size:)  1		Species?		Number of Dominant Species That Are OBL, FACW, or FAC: 5 (A	4)
2				Total Number of Dominant Species Across All Strata:  5 (B	3)
4.					٠,
5				Percent of Dominant Species That Are OBL, FACW, or FAC: 100 (A	<b>∜</b> B)
6				Prevalence Index worksheet:	
7				Total % Cover of: Multiply by:	
8				OBL species x 1 =	
		= Total Cov		FACW species x 2 =	
50% of total cover:	20% of	total cover	:	FAC species x 3 =	
Sapling/Shrub Stratum (Plot size:)				FACU species x 4 =	
1				UPL species x 5 =	
2				Column Totals: 0 (A) 0 (	(B)
3				Column Totals (A) (	(ロ)
4				Prevalence Index = B/A =	
5				Hydrophytic Vegetation Indicators:	
6				1 - Rapid Test for Hydrophytic Vegetation	
7				2 - Dominance Test is >50%	
8				3 - Prevalence Index is ≤3.0 <sup>1</sup>	
	0	= Total Cov	er er	Problematic Hydrophytic Vegetation <sup>1</sup> (Explain)	
50% of total cover:	20% of	total cover	:		
Herb Stratum (Plot size:)  1 Setaria spp.	30	yes	FAC	<sup>1</sup> Indicators of hydric soil and wetland hydrology mus be present, unless disturbed or problematic.	st
2. Campsis radicans	15	yes	FAC	Definitions of Four Vegetation Strata:	
3. Sorghum halepense	20	yes	FAC		
4 Vernonia altissima	10	yes	FAC	Tree – Woody plants, excluding vines, 3 in. (7.6 cm) more in diameter at breast height (DBH), regardless	
5. UK grass	20	ves	FAC	height.	) OI
6				Canling(Charle )0(cade plants avaleding vince la	
7				Sapling/Shrub – Woody plants, excluding vines, lest than 3 in. DBH and greater than 3.28 ft (1 m) tall.	SS
8					
9				Herb – All herbaceous (non-woody) plants, regardle of size, and woody plants less than 3.28 ft tall.	ess
10.					
11				Woody vine – All woody vines greater than 3.28 ft i height.	in
12.				Height.	
12.	95	= Total Cov			
50% of total cover:					
	20 % 01	total cover			
Woody Vine Stratum (Plot size:)					
1					
2.			-		
3					
4					
5				Hydrophytic	
50% of total cover:		= Total Cov		Vegetation Present?  Yes   No   No   No   No   No   No   No   N	
		total cover	·		
Remarks: (If observed, list morphological adaptations bel	<b>○</b> ₩ <i>)</i> .				

Sampling Point: \_\_\_\_

SOIL

Profile Desc	ription: (Describe	to the depth	needed to docur	nent the i	ndicator	or confirm	n the absence	of indicators.)
Depth	Matrix		Redo	x Features	6			
(inches)	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>	Texture	Remarks
0-18	5 YR 5/6	80%	<del></del> _				sandy loam	
		200/						
	5YR 5/4	20%						
	oncentration, D=De					ains.		PL=Pore Lining, M=Matrix.
Hydric Soil I	ndicators: (Appli	cable to all LF	RRs, unless other	wise note	ed.)		Indicators 1	for Problematic Hydric Soils <sup>3</sup> :
Histosol	(A1)		Polyvalue Be	low Surfac	ce (S8) <b>(L</b>	RR S, T, L	J) 1 cm M	uck (A9) <b>(LRR O)</b>
Histic Ep	ipedon (A2)		Thin Dark Su	rface (S9)	(LRR S,	T, U)	2 cm M	uck (A10) <b>(LRR S)</b>
Black His	stic (A3)		Loamy Muck	y Mineral (	(F1) <b>(LRR</b>	O)	Reduce	ed Vertic (F18) (outside MLRA 150A,B)
Hydroge	n Sulfide (A4)		Loamy Gleye	d Matrix (I	F2)		Piedmo	ont Floodplain Soils (F19) <b>(LRR P, S, T)</b>
Stratified	Layers (A5)		Depleted Ma					lous Bright Loamy Soils (F20)
Organic	Bodies (A6) (LRR I	P, T, U)	Redox Dark	Surface (F	6)			A 153B)
	cky Mineral (A7) (L		Depleted Dai	k Surface	(F7)		Red Pa	rent Material (TF2)
	esence (A8) (LRR I		Redox Depre				Very Sh	nallow Dark Surface (TF12)
1 cm Mu	ck (A9) (LRR P, T)		Marl (F10) (L	RR U)				Explain in Remarks)
Depleted	Below Dark Surfac	ce (A11)	Depleted Ocl	nric (F11)	(MLRA 1	51)		,
Thick Da	rk Surface (A12)		Iron-Mangan		-	-	T) <sup>3</sup> Indica	ators of hydrophytic vegetation and
Coast Pr	airie Redox (A16) (	MLRA 150A)					-	and hydrology must be present,
Sandy M	lucky Mineral (S1) (	LRR O, S)	Delta Ochric	(F17) <b>(ML</b>	RA 151)		unle	ss disturbed or problematic.
	leyed Matrix (S4)		Reduced Ver		-	0A, 150B)	1	·
	edox (S5)		Piedmont Flo					
	Matrix (S6)						RA 149A, 153C,	153D)
	face (S7) (LRR P,	S, T, U)	_	ū	`	, (	, ,	,
	ayer (if observed)							
Туре:	•							
			_				Undei a Cail I	Bracont2 Vac   No   ✓
	ches):		<del></del>				Hydric Soil	Present? Yes No
Remarks:								

## WETLAND DETERMINATION DATA FORM – Atlantic and Gulf Coastal Plain Region

Project/Site: Site E2, +/-45 Acres	City/County: Alexandria/Ra	pides	Sampling Date: 07/30/2015		
Applicant/Owner: England Authority			Sampling Point: Data Point 3		
• •	Section, Township, Range: S		. •		
	Local relief (concave, convex				
Subregion (LRR or MLRA): Lat: 31.					
Soil Map Unit Name: Coushatta silt loam (Nd)		NWI classific			
	,				
Are climatic / hydrologic conditions on the site typical for this time of					
Are Vegetation, Soil, or Hydrology significa		al Circumstances" p	oresent? Yes No		
Are Vegetation, Soil, or Hydrology naturally	problematic? (If needed,	explain any answe	rs in Remarks.)		
SUMMARY OF FINDINGS - Attach site map show	ng sampling point locati	ons, transects	, important features, etc.		
Hydrophytic Vegetation Present? Yes ✓ No	Is the Sampled Area				
Hydric Soil Present? Yes No✓	within a Wetland?	Yes	No <u> </u>		
Wetland Hydrology Present? Yes No✓		165	110		
HYDROLOGY					
Wetland Hydrology Indicators:		Secondary Indica	ators (minimum of two required)		
Primary Indicators (minimum of one is required; check all that app	ly)	Surface Soil	Cracks (B6)		
Surface Water (A1) Aquatic Fauna	[B13)	Sparsely Veg	getated Concave Surface (B8)		
High Water Table (A2) Marl Deposits (		Drainage Pa			
Saturation (A3) Hydrogen Sulfic		Moss Trim Lines (B16)			
	spheres along Living Roots (C3)				
	duced Iron (C4) duction in Tilled Soils (C6)	Crayfish Burrows (C8) (C6) Saturation Visible on Aerial Imagery (C9)			
Algal Mat or Crust (B4) Thin Muck Surf.	, ,		Position (D2)		
Iron Deposits (B5) Other (Explain	, ,	Shallow Aqui	, ,		
Inundation Visible on Aerial Imagery (B7)	•	FAC-Neutral			
Water-Stained Leaves (B9)		Sphagnum m	noss (D8) (LRR T, U)		
Field Observations:					
Surface Water Present? Yes No Depth (incl					
Water Table Present? Yes No ✓ Depth (incl					
	nes): Wetland	Hydrology Presen	nt? Yes No		
(includes capillary fringe)  Describe Recorded Data (stream gauge, monitoring well, aerial pl	notos, previous inspections), if av	ailable:			
Remarks:					
No saturation, well drained.					

VEGETATION (Four Strata) - Use scientific names of plants.

Tree Stratum (Plot size: \_\_\_\_\_)

Sapling/Shrub Stratum (Plot size: \_\_\_\_\_)

Herb Stratum (Plot size: \_\_\_\_\_)

1. Sorghum halepense

Campsis radicans

3. Ambrosia trifida

4. Vitis spp.

Absolute Dominant Indicator

% Cover Species? Status

0 \_\_\_ = Total Cover

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

0 = Total Cover 50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

yes

yes \_\_\_

yes

yes

92 = Total Cover

0 \_\_\_\_ = Total Cover

FAC

**FAC** 

FAC

FAC

50

25

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_

50% of total cover: \_\_\_\_\_ 20% of total cover: \_\_\_\_\_

7\_\_\_

10

	DP- Sampling Point:	-3
$\neg$	Dominance Test worksheet:	
	Number of Dominant Species	(A)
	Total Number of Dominant Species Across All Strata: 4	(B)
	Percent of Dominant Species That Are OBL, FACW, or FAC: 100	(A/B)
.	Barriera	
.	Prevalence Index worksheet:	
.	OBL species x 1 =	
.		
	FAC species x 3 =	
	FACU species x 4 =	
	UPL species x 5 =	
`	Column Totals: 0 (A) 0	(B)
	Prevalence Index = B/A =	
۱	Hydrophytic Vegetation Indicators:	
٠	1 - Rapid Test for Hydrophytic Vegetation	
.	2 - Dominance Test is >50%	
.	3 - Prevalence Index is ≤3.0 <sup>1</sup>	
	Problematic Hydrophytic Vegetation <sup>1</sup> (Explain	)
	<sup>1</sup> Indicators of hydric soil and wetland hydrology mube present, unless disturbed or problematic.	ıst
	Definitions of Four Vegetation Strata:	
	Tree – Woody plants, excluding vines, 3 in. (7.6 cr more in diameter at breast height (DBH), regardles height.	
	Sapling/Shrub - Woody plants, excluding vines, I than 3 in. DBH and greater than 3.28 ft (1 m) tall.	ess
	Herb - All herbaceous (non-woody) plants, regard of size, and woody plants less than 3.28 ft tall.	lless
.	Woody vine - All woody vines greater than 3.28 fl height.	t in
	_	
.		
	Hydrophytic	
	Hydrophytic Vegetation Present?  Yes No No	
_	1	

Remarks: (If ob:	served, list morp	hological ac	daptations bel	OW)
------------------	-------------------	--------------	----------------	-----

Woody Vine Stratum (Plot size: )

SOIL

Sampling Point: DP-3

Depth	Matrix		oth needed to docu Red	ox Features				,
(inches)	Color (moist)	%	Color (moist)	%	_Type <sup>1</sup>	Loc <sup>2</sup>	<u>Texture</u>	Remarks
0-18	5 YR 4/3	85%	5 YR 4/2	15%	KIVI	IVI	sandy loam	some gravel
Type: C=C	oncentration, D=De	epletion, RM	=Reduced Matrix, M	S=Masked	Sand Gr	ains.	<sup>2</sup> Location:	PL=Pore Lining, M=Matrix.
lydric Soil	Indicators: (Appl	icable to all	LRRs, unless other	erwise note	ed.)		Indicators	for Problematic Hydric Soils <sup>3</sup> :
Histoso	I (A1)		Polyvalue B	elow Surfa	ce (S8) <b>(L</b>	.RR S, T,	U) 1 cm N	Muck (A9) (LRR O)
	pipedon (A2)		Thin Dark S				<del></del>	Muck (A10) <b>(LRR S)</b>
	istic (A3)		Loamy Muc			R O)		ed Vertic (F18) (outside MLRA 150A,E
	en Sulfide (A4)		Loamy Gley		F2)			ont Floodplain Soils (F19) (LRR P, S, T
	d Layers (A5) : Bodies (A6) <b>(LRR</b>	D T III	Depleted Ma Redox Dark		·6)			alous Bright Loamy Soils (F20) RA 153B)
	ucky Mineral (A7) (I			,	,		•	arent Material (TF2)
	resence (A8) (LRR		, Redox Depr					Shallow Dark Surface (TF12)
	uck (A9) (LRR P, T		Marl (F10) (	,	- /			(Explain in Remarks)
	d Below Dark Surfa		Depleted O	chric (F11)	(MLRA 1	51)	<del></del>	,
Thick D	ark Surface (A12)		Iron-Manga				, <b>T</b> ) <sup>3</sup> Indio	cators of hydrophytic vegetation and
	rairie Redox (A16)	•	· —			', U)		tland hydrology must be present,
	Mucky Mineral (S1)	(LRR O, S)			-			ess disturbed or problematic.
	Gleyed Matrix (S4)		Reduced Ve					
	Redox (S5) d Matrix (S6)		Piedmont Fi					: 153D)
	ırface (S7) <b>(LRR P</b> ,	S. T. U)		Dright Loan	ily colla (	1 20) (11121	(A 145A, 1550	, 133 <i>b)</i>
	Layer (if observed							
Туре:								
	ches):						Hydric Soil	Present? Yes No V
Remarks:								
	4 11 11 - 4.	اء ۽ مادن						
area nis	torically distu	ırbea						

## WETLAND DETERMINATION DATA FORM – Atlantic and Gulf Coastal Plain Region

Project/Site: Site E2, +/-45 Acres	City/County: Alexand	Iria/Rapides	Sampling Date: 07/30/2015			
Applicant/Owner: England Authority	State: LA	Sampling Point: Data Point 4				
• • • • • • • • • • • • • • • • • • • •	Section, Township, Ra					
	Local relief (concave, c					
Subregion (LRR or MLRA):			Datum: NAD 83			
Soil Map Unit Name: Coushatta silt loam (Nd)		NWI classific				
	,					
Are climatic / hydrologic conditions on the site typical for t						
Are Vegetation, Soil, or Hydrology			present? Yes No			
Are Vegetation, Soil, or Hydrology	naturally problematic? (If ne	eeded, explain any answe	rs in Remarks.)			
SUMMARY OF FINDINGS - Attach site map	showing sampling point l	ocations, transects	, important features, etc.			
Listendaria Vantalia Bassaria Vantalia	N.					
	No Is the Sampled					
	No within a Wetlar	nd? Yes <u>√</u>	No			
Remarks:	NO					
Nemarks.						
HYDROLOGY						
Wetland Hydrology Indicators:		Secondary Indica	ators (minimum of two required)			
Primary Indicators (minimum of one is required; check a	II that apply)	Surface Soil				
1	ic Fauna (B13) Deposits (B15) <b>(LRR U)</b>		<ul><li>Sparsely Vegetated Concave Surface (B8)</li><li>Drainage Patterns (B10)</li></ul>			
	gen Sulfide Odor (C1)	Moss Trim Li				
	ed Rhizospheres along Living Roots		Water Table (C2)			
	nce of Reduced Iron (C4)	Crayfish Burr				
	nt Iron Reduction in Tilled Soils (C6)		isible on Aerial Imagery (C9)			
	Muck Surface (C7)		Geomorphic Position (D2)			
	(Explain in Remarks)	Shallow Aquitard (D3)				
Inundation Visible on Aerial Imagery (B7)	,	✓ FAC-Neutral Test (D5)				
Water-Stained Leaves (B9)			noss (D8) (LRR T, U)			
Field Observations:						
	Pepth (inches):					
Water Table Present? Yes No _✓ □	Depth (inches):		_			
Saturation Present? Yes No D	epth (inches): surface We	etland Hydrology Presen	nt? Yes <u>√</u> No			
(includes capillary fringe)  Describe Recorded Data (stream gauge, monitoring wel	aerial photos, previous inspections	s) if available:				
Beschibe Necorded Bata (Stream gauge, monitoring wer	, acriai priotos, previous irispections	s), ii availabio.				
Remarks:						
	_					
Some pools of inundation within drain	1.					

Sampling Point: \_\_\_

		Dominant		Dominance Test worksheet:
Tree Stratum (Plot size:)  1		Species?		Number of Dominant Species That Are OBL, FACW, or FAC: 4 (A)
2.				
3.				Total Number of Dominant Species Across All Strata:  4 (B)
4				Species / Isl 655 / III Strata.
5.				Percent of Dominant Species  That Are ORL FACIAL or FACIAL 100
6				That Are OBL, FACW, or FAC: 100 (A/B)
				Prevalence Index worksheet:
7				Total % Cover of: Multiply by:
8	0 :			OBL species x 1 =
500/-5/-/-				FACW species x 2 =
50% of total cover:	20% of	total cover	·	FAC species x 3 =
Sapling/Shrub Stratum (Plot size:)				FACU species x 4 =
1				UPL species x 5 =
2				Column Totals: 0 (A) 0 (B)
3				Column Totals. (A)
4				Prevalence Index = B/A =
5				Hydrophytic Vegetation Indicators:
6				1 - Rapid Test for Hydrophytic Vegetation
7				2 - Dominance Test is >50%
8				3 - Prevalence Index is ≤3.0¹
	0	= Total Cov	er er	Problematic Hydrophytic Vegetation (Explain)
50% of total cover:				1 Toblematic Hydrophytic vegetation (Explain)
Herb Stratum (Plot size:)				
1. Juncus effusus	50	yes	FACW	<sup>1</sup> Indicators of hydric soil and wetland hydrology must be present, unless disturbed or problematic.
2 Typha latifolia	10	ves	OBL	Definitions of Four Vegetation Strata:
3. Cyperus spp.	20	ves	FACW	John Morio of Four Vogotation Grata.
4 Juncus spp.	10	yes	FACW	Tree – Woody plants, excluding vines, 3 in. (7.6 cm) or
**-				more in diameter at breast height (DBH), regardless of height.
5				
6				Sapling/Shrub – Woody plants, excluding vines, less than 3 in. DBH and greater than 3.28 ft (1 m) tall.
7				than 3 iii. DBH and greater than 3.20 it (1 iii) taii.
8				Herb – All herbaceous (non-woody) plants, regardless
9				of size, and woody plants less than 3.28 ft tall.
10				Woody vine – All woody vines greater than 3.28 ft in
11				height.
12				
	90	= Total Cov	⁄er	
50% of total cover:	20% of	total cover	:	
Woody Vine Stratum (Plot size:)				
1				
2				
3				
4.				
5.				Hydranbytia
	0 :	= Total Co	 /er	Hydrophytic Vegetation
50% of total cover:				Present? Yes V No No
Remarks: (If observed, list morphological adaptations bel		total cover		
Remarks. (II observed, list morphological adaptations bel	iOW).			

Sampling Point: \_\_\_\_

SOIL

Profile Desc	ription: (Describe	to the dept	h needed to docu	ment the	indicator	or confirm	m the absence	of indicators.)
Depth	Matrix		Redo	ox Feature	es			
(inches)	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>	Texture	Remarks
0-18	5 YR 4/3	50%	5 YR 4/2	40%	KIVI	IVI	sandy loam	some gravel
			5 YR 4/1	10%	KIVI	IVI		
			3 TK 4/ I	- 10%	- <del> </del>			
						. —		
	oncentration, D=Dep					ains.		PL=Pore Lining, M=Matrix.
Hydric Soil I	ndicators: (Applic	able to all	LRRs, unless othe	rwise not	ted.)		Indicators	for Problematic Hydric Soils <sup>3</sup> :
Histosol	(A1)		Polyvalue B	elow Surfa	ace (S8) <b>(</b> I	LRR S, T,	U) 1 cm N	Muck (A9) (LRR O)
Histic Ep	ipedon (A2)		Thin Dark S	urface (S9	9) (LRR S,	T, U)	2 cm M	Muck (A10) (LRR S)
Black His	stic (A3)		Loamy Muck	ky Mineral	(F1) (LRF	₹ 0)	Reduc	ed Vertic (F18) (outside MLRA 150A,B)
Hydroge	n Sulfide (A4)		Loamy Gley	ed Matrix	(F2)		Piedm	ont Floodplain Soils (F19) (LRR P, S, T)
Stratified	l Layers (A5)		Depleted Ma	atrix (F3)			Anoma	alous Bright Loamy Soils (F20)
Organic	Bodies (A6) (LRR P	P, T, U)	Redox Dark	Surface (	F6)		(ML	RA 153B)
	cky Mineral (A7) (LI		Depleted Da	ırk Surfac	e (F7)		✓ Red P	arent Material (TF2)
	esence (A8) (LRR L		Redox Depr				Very S	Shallow Dark Surface (TF12)
1 cm Mu	ck (A9) (LRR P, T)		Marl (F10) (I	LRR U)				(Explain in Remarks)
Depleted	Below Dark Surfac	e (A11)	Depleted Oc	hric (F11)	(MLRA 1	51)	<del></del>	
Thick Da	rk Surface (A12)		Iron-Mangar		-		, <b>T</b> ) <sup>3</sup> Indic	cators of hydrophytic vegetation and
Coast Pr	airie Redox (A16) (I	VILRA 150A						tland hydrology must be present,
Sandy M	lucky Mineral (S1) (	LRR O, S)	Delta Ochrid		-		unl	ess disturbed or problematic.
	leyed Matrix (S4)	, ,	Reduced Ve		-	50A, 150B		•
	edox (S5)		Piedmont FI					
	Matrix (S6)						RA 149A, 153C	c. 153D)
	face (S7) (LRR P, \$	S. T. U)	_	J	,	, , ,	,	,
	ayer (if observed)						1	
Туре:	, (,							
	-h).							. B 1
	ches):						Hydric Soil	Present? Yes V No V
Remarks:								

## WETLAND DETERMINATION DATA FORM – Atlantic and Gulf Coastal Plain Region

Project/Site: Site E2, +/-45 Acres	City/County: Alexar	ndria/Rapides	Sampling Date: 07/30/2015		
Applicant/Owner: England Authority			Sampling Point: Data Point 5		
• • • • • • • • • • • • • • • • • • • •	Section, Township, F		. •		
			vel Slope (%): 1-2		
Subregion (LRR or MLRA): Lat:					
Soil Map Unit Name: Coushatta silt loam (Nd)		NWI classific			
Are climatic / hydrologic conditions on the site typical for this tir					
Are Vegetation, Soil, or Hydrology sign		e "Normal Circumstances" p	oresent? Yes No		
Are Vegetation, Soil, or Hydrology natu	rally problematic? (If	needed, explain any answe	rs in Remarks.)		
SUMMARY OF FINDINGS - Attach site map sh	owing sampling point	t locations, transects	, important features, etc.		
Hydrophytic Vegetation Present? Yes ✓ No _					
Hydric Soil Present? Yes No _	/ is the Sample		,		
Wetland Hydrology Present? Yes No _		land? Yes	No <u> </u>		
Remarks:					
HYDROLOGY					
Wetland Hydrology Indicators:		Secondary Indica	ators (minimum of two required)		
Primary Indicators (minimum of one is required; check all that	apply)	Surface Soil	Cracks (B6)		
Surface Water (A1) Aquatic Fat	una (B13)		getated Concave Surface (B8)		
<u> </u>	sits (B15) (LRR U)	Drainage Patterns (B10)			
	Sulfide Odor (C1)	Moss Trim Li			
Water Marks (B1) Oxidized R	hizospheres along Living Roo				
Sediment Deposits (B2) Presence o	f Reduced Iron (C4)	Crayfish Burrows (C8)			
Drift Deposits (B3) Recent Iron	Reduction in Tilled Soils (Ce				
	Surface (C7)	Geomorphic Position (D2)			
	ain in Remarks)	Shallow Aqui			
Inundation Visible on Aerial Imagery (B7)		FAC-Neutral	` '		
Water-Stained Leaves (B9)		Sphagnum n	noss (D8) (LRR T, U)		
Field Observations:					
Surface Water Present? Yes No ✓ Depth					
Water Table Present?  Yes No Depth					
Saturation Present? Yes No ✓ Depth (includes capillary fringe)	(inches): V	Netland Hydrology Presen	nt? Yes No		
Describe Recorded Data (stream gauge, monitoring well, aeri	al photos, previous inspectio	ns), if available:			
Remarks:					
No saturation, well drained.					

Sampling Point: \_\_

		Dominant		Dominance Test worksheet:					
Tree Stratum (Plot size:)  1		Species?		Number of Dominant Species That Are OBL, FACW, or FAC: 3 (A)					
2. 3.				Total Number of Dominant Species Across All Strata: 4 (B)					
4 5				Percent of Dominant Species That Are OBL, FACW, or FAC: 75 (A/B)					
6				Prevalence Index worksheet:					
7				Total % Cover of: Multiply by:					
8				OBL species x 1 =					
		= Total Co		FACW species x 2 =					
50% of total cover:	20% of	total cover	·:	FAC species x 3 =					
Sapling/Shrub Stratum (Plot size:)				FACU species x 4 =					
1				UPL species x 5 =					
2				Column Totals: 0					
3				Column Totals: (A) (B)					
4				Prevalence Index = B/A =					
5				Hydrophytic Vegetation Indicators:					
6				1 - Rapid Test for Hydrophytic Vegetation					
7				2 - Dominance Test is >50%					
8				3 - Prevalence Index is ≤3.0 <sup>1</sup>					
		= Total Co		Problematic Hydrophytic Vegetation <sup>1</sup> (Explain)					
50% of total cover:	20% of	total cover	·						
Herb Stratum (Plot size:)	25		ГЛС	<sup>1</sup> Indicators of hydric soil and wetland hydrology must					
1. Sorghum halepense	_ 35	yes	FAC	be present, unless disturbed or problematic.					
2. Setaria spp.	20	yes	FAC	Definitions of Four Vegetation Strata:					
Ambrosia trifida		yes	FAC	Tree – Woody plants, excluding vines, 3 in. (7.6 cm) or					
4. Trifolium repens 5	_ <u>15</u>	yes	<u>FACU</u>	more in diameter at breast height (DBH), regardless of height.					
6				Sapling/Shrub – Woody plants, excluding vines, less than 3 in. DBH and greater than 3.28 ft (1 m) tall.					
7				unan o m. BBrrana groater than o.20 it (1 m) tail.					
8				Herb – All herbaceous (non-woody) plants, regardless					
9				of size, and woody plants less than 3.28 ft tall.					
10				Woody vine - All woody vines greater than 3.28 ft in					
11				height.					
12									
	90 = Total Cover								
50% of total cover:	20% of	total cover	·						
Woody Vine Stratum (Plot size:)									
1									
2									
3									
4									
5				Hydrophytic					
	0	= Total Co	ver	Vegetation					
50% of total cover:	20% of	total cove	:	Present? Yes Ves No Ves					
Remarks: (If observed, list morphological adaptations below).									
	,								

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.)										
Depth Matrix Redox Features										
(inches)	Color (moist)	%	Color (moist)	%	Type <sup>1</sup>	Loc <sup>2</sup>	<u>Texture</u>	Remarks		
0-18	5 YR 5/8	85%	5 YR 4/2	15%	KIVI	IVI	sandy loam	some gravel		
						-	· <del></del>			
	oncentration, D=De					rains.	<sup>2</sup> Location:	PL=Pore Lining, M=Matrix.		
Hydric Soil	Indicators: (Appli	cable to all l	LRRs, unless othe	rwise not	ed.)		Indicators	for Problematic Hydric Soils <sup>3</sup> :		
Histosol	(A1)		Polyvalue Be	elow Surfa	ce (S8) (I	LRR S, T,	<b>U)</b> 1 cm l	Muck (A9) <b>(LRR O)</b>		
Histic E	pipedon (A2)		Thin Dark S	urface (S9	) (LRR S,	T, U)	2 cm l	Muck (A10) (LRR S)		
Black Hi	istic (A3)		Loamy Muck			₹ 0)	Reduc	ced Vertic (F18) (outside MLRA 150A,B)		
Hydroge	en Sulfide (A4)		Loamy Gley	ed Matrix	(F2)		Piedm	Piedmont Floodplain Soils (F19) (LRR P, S, T)		
Stratified	d Layers (A5)		Anom	Anomalous Bright Loamy Soils (F20)						
	Bodies (A6) (LRR		Redox Dark		*		•	RA 153B)		
	ucky Mineral (A7) <b>(L</b>		Depleted Da					arent Material (TF2)		
	resence (A8) (LRR	•	Redox Depr	*	8)			Very Shallow Dark Surface (TF12)		
	ıck (A9) <b>(LRR P, T)</b>		Marl (F10) (I	•			Other	(Explain in Remarks)		
	d Below Dark Surfa	ce (A11)	Depleted Oc		•	•	. <b></b>			
	ark Surface (A12)		Iron-Mangar					cators of hydrophytic vegetation and		
	rairie Redox (A16) (							tland hydrology must be present,		
	Mucky Mineral (S1)	(LKK U, S)	Delta Ochric		-			ess disturbed or problematic.		
	Gleyed Matrix (S4) Redox (S5)		Reduced Ve Piedmont Fl							
	Matrix (S6)						43A) RA 149A, 1530	· 153D)		
	rface (S7) (LRR P,	S T III		Dright Loa	illy colls	(1 20) <b>(IIIL</b> I	IIA 140A, 100C	, 1000)		
	Layer (if observed									
Type:	<b>_</b> ayor ( oboo! *ou	<i>,</i> .								
l	ah a a):						Undria Cal	I Draggard 2 Vag   No		
Depth (in	cnes):						Hydric Soi	Present? Yes No		
Remarks:										
area his	torically distu	rbed, old	d tank farm lo	ocation	1					
	, , , , , , , , , , , , , , , , , , , ,	, ,								